




CDVI


31, av. du Gal Leclerc
 93500 PANTIN FRANCE
 Tel : 33 (0)1 48 91 01 02
 Fax : 33 (0)1 48 91 21 21
 www.cdvi.com

BMU

Module de raccordement



Cavalier en ST3



Mode PC ou Modem
 cavalier en ST2

Mode Minitel
 Cavalier en ST1




CDVI


31, av. du Gal Leclerc
 93500 PANTIN FRANCE
 Tel : 33 (0)1 48 91 01 02
 Fax : 33 (0)1 48 91 21 21
 www.cdvi.com

BMU

RS232 Interface Unit



ST3 Jumper



PC or Modem
 Jumper set on ST2

ST1 Jumper off